



# RJ45 ADAPTOR COMPATIBILITY MATRIX

## TOYOTA

XRS-RJ45W1 / XRS-RJ45R1**		XRS-RJ45W2 / XRS-RJ45R2	
<b>FJ Cruiser</b> (2011 - 2016) *Roof Console only	<b>Tacoma</b> (2012 - 2018) *Left hand side of steering wheel (LHD)	<b>FJ Cruiser</b> (2007 - 2018)	<b>Landcruiser 70 Series</b> *Plastic Dash
<b>Hilux</b> (9/2015 - Current)	<b>Highlander</b> (2001 - 2018)	<b>Fortuner</b> (2005 - 2015)	<b>Landcruiser 79</b> (2021-Current) *Centre Console
<b>Landcruiser 79</b> (2021-Current) *Right hand side of steering wheel	<b>4Runner</b> (2010 - 2014)	<b>Hiace</b> (2005 - 2013)	<b>4Runner</b> (2003 - 2009)
<b>Landcruiser 200</b> (2008 - 2021)	<b>Fortuner</b> (2016 - Current)	<b>Hilux</b> (2005 - 2015)	<b>Kluger</b> (2001 - 2007)
<b>Prado 150</b> (2010 - 2018) *2018 onwards only on right hand side of steering wheel	<b>Hiace</b> (2014 - 2018)	<b>Landcruiser 100</b> (1998 - 2007)	<b>Prado 120</b> (2003 - 2009)
<b>RAV4</b> (2006 - 2018)	<b>Kluger</b> (2008 - 2018)	<b>Tacoma</b> (2005-2022)	<b>Tundra</b> (2005-2007) *Centre Console
<b>Tacoma</b> (2016 - 2022)			

\*\*Ford Rangers and Holden Colorado require an aftermarket fascia to install additional switches and adaptors. Common aftermarket fascia available use the Type 1 (XRS-RJ45W1 or XRS-RJ45R1) style adaptor.

These fascia are NOT sold through GME.

For coloured XRS illumination, connect the red wire to the vehicles positive and the black wire to vehicle earth.



# RJ45 ADAPTOR COMPATIBILITY MATRIX

## TOYOTA

XRS-RJ45T5		XRS-RJ45W10 / XRS-RJ45R10	XRS-RJ45W11 / XRS-RJ45R11
<b>Prado 150</b> (2018 - Current)	<b>Kluger</b> (12/2019 - Current)	<b>Landcruiser 79</b> (2021 - Current)	<b>Landcruiser 70 Series</b> (2024 – Current) *Air Con Panel
<b>Prado 250</b> (2024-Current)	<b>Landcruiser 300</b> (2022 - Current)		<b>Landcruiser 70 Series</b> (2009 – 2023) *Air Con Panel
<b>RAV4</b> (6/2019 - Current)	<b>Landcruiser Face-lift 70 Series</b> (2024 - current) *Center Console		<b>Landcruiser 70 Series (Horizontal)</b> (1984 – 2009)
<b>Hiace</b> (5/2019 - Current)	<b>Tacoma</b> (2024 - Current)		<b>Landcruiser 80 Series (Horizontal)</b> (1990 – 1997)
<b>Camry</b> (2018 - Current)	<b>Tundra</b> (2022 - Current)		<b>Hilux</b> (1993 – 1997)




## RJ45 ADAPTOR COMPATIBILITY MATRIX

NISSAN		ISUZU
XRS-RJ45W3 / XRS-RJ45R3	XRS-RJ45W8 / XRS-RJ45R8	XRS-RJ45W4 / XRS-RJ45R4
<b>Patrol GU Series 4-8</b> (2004 - 2018)	<b>Navara NP300</b> (2016 - Current)	<b>D-Max 2nd Generation</b> (2012 - 2020) *Lower Switch Fascia under A/C Controls where fitted
<b>Patrol Y62</b> (2016 - Current)	<b>Pathfinder R52</b> (2012 - 2020)	<b>MU-X 1st Generation</b> (2012 - 2021) *Lower Switch Fascia under A/C Controls where fitted
<b>X-Trail T31</b> (2007 - 2014)	<b>X-Trail T32</b> (2014 - 2022)	
<b>Pathfinder R51</b> (2005 - 2012)		
<b>Navara D40</b> (2008 - 2014)		
<b>Navara NP300</b> (2016 - Current) *Handbrake Console		



# RJ45 ADAPTOR COMPATIBILITY MATRIX

ISUZU / MAZDA	MITSUBISHI	UNIVERSAL	
XRS-RJ45T7	XRS-RJ45W9 / XRS-RJ45R9	XRS-RJ45RND	XRS-RJ45W6 / XRS-RJ45R6
BT-50 3rd Generation (10/2021 - Current)	Triton MQ (2015 - 2018)	Universal Fitment into a 25mm Round Hole	Suits Carling Style Dash Hole Dimensions
D-Max 3rd Generation (9/2021 - Current)	Triton MR (2019 - 2023)		
MU-X 2nd Generation (2022 - Current) *Models without heated seats	Pajero Sport KR, KS, QE (2015 - 2021)		
	Outlander ZK (2012 - 2021)		
		